





FIG. 1









FAT & TRAC	EMARKS			6/10	0				
BRG ~ 300B									
BRG		615	618		-627	<del>-</del>	-633		
1168		CONN REQ	RINGING /	VIO	<b>\</b>			555 637	5
CMTS ~ 116B			. <b> I</b>	- L	NOIL THE CONNECTION	629	REPORT NEXT OFF HOOK	ζ(	
		SETUP —612	CK — 616	CONNECT — 622	טבונ	REPORT —	PORT NE	RELEASE GATE	E 00
CM ~ 218	- 610	SET	SETUP ACK 616 ALERTING 619	CONNE	Ŷ,	REI	2 H	CATE BEI COMPLETE	אור וורר
₹-₹	7	#	719	]- <b>'-</b> -			Y T	7-7	
122	9 LNP QUERY	ROUTING #	ION ACK —		.625 — 626		- REI FASE GATE	MPLETE	
IP LNP (	S ~ 609	611 ROUT		623	/ / / \			L	
116A 100K ~	DIALED DIGITS ~		GAIE ALLOCATION  GATE ALLOC  AI FRIING	CONVERSATION 623	DELETE CONNECTION	- ON HOOK		GATE REL	
CMTS ~ 116A		CALL PROCEEDING,	(1 - 1 - 1	CONVE	DELETE	177	T NEXT	1	
(	5	[ ]	0 4 )		ON HOOK — 624	628 -	~ REPOR	636	
. 6 ~ 300A	DIAL TONE	613			ON HOC		632		
FIG.		*		J	L_L_	¥_L_	1		






## 1999-0283 REPLACEMENT SHEET

7/10

FIG. 7







1999-0283 REPLACEMENT SHEET

8/10

FIG. 8





10/10

FIG. 10

